




# GENOA SHEETING ANGLES.



LIGHT WINDS 0-6 KNOTS.  
SHEETING LINE AS PER  
DIAGRAM, BUT SHEET  
IS EASED.



MED WINDS 7-16 KNOTS.  
SHEETING LINE AS PER  
DIAGRAM, SHEET IS TIGHT.



STRONG WINDS 17-25KNOTS.  
SHEETING AS PER DIA-  
GRAM ,SHEET IS TENSIONED  
HARD.